


















Detour Route for the Damaged Index-Galena Road

Key to Features:



-  Project Location
-  Flood Damage Repair Location
-  Photo Location
-  Unnamed Creeks
-  Creeks
-  Rivers
-  County Line
-  Highway 2
-  Major Forest Service Roads
-  Other Roads
-  Current Access to Skyko 3/4
-  Wild Sky Wilderness Area
-  U.S. Forest Service Land
-  City of Index / City of Skykomish
-  Skyko Subdivision



0.5 0 0.5 1 Mile



Snohomish County disclaims any warranty of merchantability or warranty of fitness of this map for any particular purpose, either express or implied. Any user of this map assumes all responsibility for use thereof, and further agrees to hold Snohomish County harmless from and against any damage, loss, or liability arising from any use of this map.



Current Conditions on the Ground



Photo 01
This photo shows a portion of the existing road corridor from Milepost 6.4. Looking up valley, the new side channel still flows down the existing road corridor. The inset details the spot at which the water returns back towards the river.



Photo 02
This photo looks downstream from the upper end of the new side channel. Of particular note is the volume of water found in the new side channel.




Photo 03
Looking downstream, this photo shows the damage located approximately at Milepost 10.9.



Photo 04
Located approximately at Milepost 13, this gully on Troublesome Mountain frequently deposits a large amount of rock debris onto the road, hindering access to the upper valley.



Photo 05
This photo shows the steep switchbacks below Jack's Pass located on the north side of the pass. Without the assistance of snow removal during winter, negotiating the road is quite hazardous.



Photo 06
This photo looks southeast, from above Jack's Pass. Despite a modest elevation of 2,500 feet, winter snowfall prevents year-round access of the North Fork Skykomish River valley.